





Communication and Integrity  
in  
Products Liability

## *The Broken Forklift*



- A hydraulic cylinder on a forklift comes apart dropping a large steel frame which pins and severs several fingers of a worker guiding the frame.
- Review showed that the screw in the cylinder was never inserted correctly and improper maintenance was the cause.
- The matter would have been litigated based upon failure to follow recommended repair and maintenance procedures

### *Attorney Referral*

John's report and his excellent photographic work made it crystal clear that these rods had not been moved because the paint had not been disturbed. In addition, John also assisted me in connection with the mechanics and physical forces that affect the operation of a forklift. Due to John's assistance and expertise, this case was settled for a substantial sum. Finally, he was cooperative and responsive to my many inquiries.